

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 44 .. NR 20-21 W.

----- Alger -----

----- COUNTY

DESCRIPTION OF CORNER .. Section Corner common to Sections 1, 12, 6, 7 ..

DESCRIPTION OF CORNER MONUMENT .. 1" pipe with 4" brass cap ..

WITNESSES TO CORNER .. 8" Tamarack .. N 65° E .. 12 links ..

----- 8" Spruce .. S 38° E .. 9½ links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Section Corner from one Tamarack B.T. in good condition.

Corner is at intersection of N. and W. road.

Corner shown to us by Arne Metsa, District Forester.

Corner placed and witnessed April 17, 1956.

SURVEYORS SEAL

SIGNED

Billy D. Buckles

REGISTERED LAND SURVEYOR

DATE

4/19/56