

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 44 NR. 22W

Alger COUNTY

DESCRIPTION OF CORNER 1/4 cor. between secs: 32-33

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 14" W. Pine (1/4s NBT) S60°W 58 Lks.

10" Cedar (1/4s NBT) N84°W 26 1/2 Lks.

9" Cedar (1/4s NBT) S51°E 09 Lks.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced cor. from two Tamarack B.Ts. in place. NW B.T. is in good condition. SE B.T. is down and in poor condition. Found 2" iron pipe and wood post in place Cor. lies in swamp. Cor. placed and wit. 2/24/59 with Art Enger, Ass't D.F.

SURVEYORS SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 8/11/59
REGISTERED LAND SURVEYOR