

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T~~44~~ NR 22W

Alger

COUNTY

DESCRIPTION OF CORNER 1/4 cor. between secs: 29-32

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 8" Cedar (1/4s NBT) N17°W 23 Lks.

6" Cedar (1/4s NBT) S15°E 25 Lks.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced cor. from one Cedar B.T. bearing S12°W 23 Lks. Cedar down and in good condition. Cor. lies in swamp. Cor. placed and wit. 2/24/59 with Art Enger, Ass't D.F.

SURVEYORS SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 8/11/59
REGISTERED LAND SURVEYOR