

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 44. NR. 22 W. . .

Alger

COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 18 and 19

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 10" Cedar S 20° W 69 1/2 links

5" Cedar N 2° E 44 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 Corner from one Cedar B.T. in good condition.

Corner lies in center of E. and W. corduroy road.

Corner shown to us by Arne Metsa, District Forester.

Corner placed and witnessed April 17, 1956.

SURVEYORS SEAL

SIGNED

Billy D. Buckles
REGISTERED LAND SURVEYOR

DATE 4/19/56