

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 44 .. NR. 22 W ..

----- Alger ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 16, 17, 20, 21

DESCRIPTION OF CORNER MONUMENT Pipe not set

WITNESSES TO CORNER 9" Cedar S 52° E 81½ links

9" Cedar S 57° W 114½ links

Cedar post set 2 rods north of corner.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-witnessed Corner from one Yellow Birch B.T. in good condition.

Corner is in approximate center of E. and W. Co. Road.

Corner re-witnessed April 17, 1956.

SURVEYORS SEAL

SIGNED

*Billy D. Sweeney*  
REGISTERED LAND SURVEYOR

DATE 4/19/56