

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

Marquette and  
Alger COUNTY

T 44 N R 's 22 & 23 W


T44N 24/19 T44N  
R23W 25/30 R22 W

DESCRIPTION OF CORNER Section corner for Sections

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 9/15/71 F. J. Bray

WITNESSES TO CORNER..... 9" Cedar (S.30) (NBT) S82°E, 14.2'



7" Cedar (S.25) (NBT) S68°W, 13.4'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from an old down wood post which checks well with badly rotted Tamarack stump to the northeast for bearing and distance. Signature tree near dates back to over forty years ago. Corner was shown to me by Foresters Zuidema and Conley.

SURVEYOR'S SEAL

SIGNED

Frank J. Bray  
REGISTERED LAND SURVEYOR  
Frank J. Bray

DATE

12-9-71

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68