

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Alger COUNTY
T 44 N R 22 W

DESCRIPTION OF CORNER 1/4 corner for Sections $\frac{19}{30}$

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 9/15/71 F. J. Bray

WITNESSES TO CORNER..... 9" Cedar ($\frac{1}{8}$) (NBT) S52°E, 27.9'



6" Cedar ($\frac{1}{8}$) (NBT) S28°E, 10.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from down rotted B. Ash to the southwest which faces both rotted. In 1959 this B.T. was a dead stub with scribe mark visible according to note in Field Note Book by A. O. Eger, Forester. This corner shown to me by Foresters Zuidema and Conley.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J. Bray

DATE

12-9-71

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68