## LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	T S., R W.		
2. PROPERTY CONTROLL 15 ING IN SECTION	T. 45 8., R. 21 W.	_15	
3. MISCELLANEOUS PROPERTY IN SECTION,	T N. R E.		
4. LOT NO, RECORDED PLAT			
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER

do hereby certify that under requirements of P.A.74, Michigan P.A. of 1970, David B. Babbitt the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on December 10 1981, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_ 19\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

- A. Description of original monument and accessories and/or subsequent restoration:
- W 1/16 corner on the South section line of Section 15; not previously established.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

15 Set M.P.O.L. between the South 1/4 corner and the S.W. Sec. corner of Section 15.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: 1" pipe, 4" aluminum cap

15 4" Hard Maple - N28°E - 39.6'; 6" Hard Maple - N46°E - 49.7'; Power Pole - S54°W -35.0'; 9" Balsam - S20°E - 33.6'.