

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 45 NR. 22W

Alger COUNTY

DESCRIPTION OF CORNER 1/4 cor. between secs: 1-12

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 18" Cedar (1/4s NBT) S70° W 66 1/2 Lks.

12" H. Maple (1/4s NBT) N85° E 13 Lks.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced cor. from one Elm B.T. bearing NW and Y. Birch stp. bearing SE. Both stumps in poor condition. Cor. lies on old blaze line east and west. Cor. placed and wit. 2/24/59 with Art Enger, Ass't D.F.

SURVEYORS SEAL

SIGNED *Billy D. Buckler*  
Billy D. Buckler  
REGISTERED LAND SURVEYOR  
DATE 8/11/59