

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 46 N.R. 17-18 W


Alger COUNTY

DESCRIPTION OF CORNER Section Corner for Secs. 1 & 2 T46N R18W 1-2 & 6-7 T46N R17W

CORNER MONUMENT 1 1/2" Iron Pipe with 3" Brass Cap

DATE MONUMENT PLACED AND WITNESSED 7/1/65 with Miller

WITNESSES TO CORNER..... 12" Hemlock (S12 NBT), S 64° W, 16 lks.



11" Hemlock (S1 NBT), N 08° W, 32 lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was set by County Surveyor dated 1915. Checks with several stumps badly rotted which possibly were Original BT's.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 2/10/1966
REGISTERED LAND SURVEYOR