

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 46. NR. 17. W

A l g e r . . . . . COUNTY

DESCRIPTION OF CORNER ~~Section corner common to Sections 8, 9, 16, 17.~~ . . .

DESCRIPTION OF CORNER MONUMENT . . . 2" Iron Pipe with 3" Brass Cap . . .

WITNESSES TO CORNER . . . 12" Cedar . . . (S 9 NBT) . . . N 58° E . . . 37 Links . . .

. . . 10" Cedar . . . (S 17 NBT) . . . S 26° W . . . 22 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED. This corner was re-witnessed. Corner dated November 7, 1917 initialed

H. J. H and G. L. D.

Corner was ~~planned~~ and witnessed August 16, 1960.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 9/15/60  
REGISTERED LAND SURVEYOR  
Billy D. Buckler