## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T 46 NR 17 W

	-	A_1_g_o_r_	COUNTY
DESCRIPTION OF CORNER	Section_corner	common to Section	2, 3, 10, 11
DESCRIPTION OF CORNER	MONUMENT	2ª Iron Pipe_with	3" Brass Cap
WITNESSES TO CORNER .	8º Klm	(S 10 MBT) S	3 80° W 20 I4nks
	8º Kla	(s_11_1BT) §	3 48° E 13 1/2 14nks

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was re-witnessed as set by unknown party. Checks with double proportionate measurement with in 9 links N & S and 2 links E & W.

Corner was placed and witnessed August 5, 1960.

SURVEYORS SEAL

SIGNED Silly D. Buckles DATE 9/14/60 Billy D. Buckler