CONS. 4047 4/56

MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T 46 NR 17 W

				<u> </u>	COUNTY
DESCRIPTION	OF	CORNER	1/4 corner betw	en_Sections_10_a	nd_111
DESCRIPTION	OF	CORNER	MONUMENT	1" Iron Pipe wit	h 4" Brass Cap
WITNESSES	то	CORNER	10" Elm	(1/4s_NBT)	#1 Links _
			7" Blm	(1/ba NBT)	21_1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was placed midway and on line between Section corners. No evidence of original corner.

Corner was placed and witnessed August 5, 1960.

SURVEYORS SEAL

SIGNED Silly O Surfely DATE 9/14/60 _ REGISTERED LAND SURVEYOR

Billy D. Buckler