

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 46. NR. 17. W

A l g e r COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 10 and 15

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 12" Cedar (1/4s NBT) N 79° E 32 Links

6" Cedar (1/4s NBT) N 43° W 32 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was placed midway and on line between section corners. No evidence of original corner.

Corner was placed and witnessed August 12, 1960.

SURVEYORS SEAL

SIGNED

*Billy D. Buckler*  
REGISTERED LAND SURVEYOR  
Billy D. Buckler

DATE 9/15/60