

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 46 NR. 17

_____ COUNTY

DESCRIPTION OF CORNER 1/4 corner for sections 1 & 2

DESCRIPTION OF CORNER MONUMENT " pine with 2" nails on

WITNESSES TO CORNER 10" iron pipe, 37°, 1 1/2 links, "1/2" up

9" iron pipe, 31°, 1 1/2 links, "1/2" up

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR

RESTORED. Re-located 1/4 corner as set by unknown surveyor. Found 2" iron pipe in loc. near iron tree (map), bearing 80°, 1 1/2 links, 1" diameter iron tree, bearing 72°, 1 1/2 links. (map) noted, evidence of tree as on plot. Corner monument set by District Forester and J. Lockall, District. Corner placed and witnessed 3-4-58.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 3-17-58
REGISTERED LAND SURVEYOR