

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 46-47 NR. 17 W. . .

Alger COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 2, 3, 34, 35 . .

DESCRIPTION OF CORNER MONUMENT No new pipe set . . . . .

WITNESSES TO CORNER 7" Cedar S 77° E 29 links . . . . .

12" Cedar S 23° W 34 links . . . . .

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-witnessed Section Corner 1 1/2" Iron Pipe with 2 1/2" brass cap in place by unknown surveyor.

One Cedar B.T. in place fair condition.

Corner lies in swamp.

Corner found by Forestry Division Survey crew while making a partial re-survey of this area.

Corner witnessed August 27, 1956.

SURVEYORS SEAL

SIGNED *Billy D. Buckler* DATE 9/4/56  
REGISTERED LAND SURVEYOR