

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T 46 N R 17 W
T 47 N R 17 W

----- Alger ----- COUNTY

DESCRIPTION OF CORNER 1/4 Section Corner between Sections 36 and 1. -----

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap. -----

WITNESSES TO CORNER 10" Cedar N 26° E 32 links -----

----- 12" Cedar S 76° E 36 1/2 links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

Replace 1/4 Corner from one Spruce B.T. in poor condition.

1/4 Corner is 23 1/2 links South and 16 links East of 40.00 ch. marker from
east.

Corner placed and witnessed January 24, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 2/16/56
REGISTERED LAND SURVEYOR