MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_46. NR_17_ #

Alger(JOUNIY
DESCRIPTION OF CORNER 1/4 Corner between Sections 23 & 26	·
DESCRIPTION OF CORNER MONUMENT_13 Pipe with 27 Brass cap	
WITTNESSES TO CORNER	
_ S"_ Gedar = N_50 N = 7 Links	
8" Cedar - N 35 E - 8 Links	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Perestry Division survey erew, while making a partial reservey of this Township. Corner had been proviously located by waknown Serveyor. Two original B.T.'s still in place, in good condition.

Corner was witnessed May 6, 1953.

SURVEYORS SEAL

SIGNED LAND SURVEYOR DATE 1/21/54