## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T 46 NR 17 V

			AlgerCOUNTY
DESCRIPTION	OF	CORNER	1/4_Cerner_between_Sections_16_8_21
DESCRIPTION	OF	CORNER	MONUMENT_1 Pipe with 4" Brass sap
WIT TNESSES	то	CORNER	
			12" Cedar - N 57 % - 8 Links
			10" Ceder - 8 25 W - 17 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Ferestry Division survey crew, while making a partial resurvey of this Tewnship. One original B.T. still in place, in good condition.

Corner was placed and witnessed September 1, 1953.

SURVEYORS SEAL

SIGNED LAND SURVEYOR DATE 1/21/54