

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 46. NR. 17. W

Alger COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 3 and 4

DESCRIPTION OF CORNER MONUMENT 1" Iron Pipe with 4" Brass Cap

WITNESSES TO CORNER 10" Cedar (1/4s NBT) N 30° W 43 Links

7" Cedar (1/4s NBT) S 23° W 11 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced from Spruce 10" S 35° E 15 Links in poor condition. Iron Marks visible (BT)

Corner was placed and witnessed August 4, 1960.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 8/12/60  
REGISTERED LAND SURVEYOR  
Billy D. Buckler