

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 46 N.R. 17W


Alger COUNTY

DESCRIPTION OF CORNER 1/4 Cor. bet. Secs. 8-9.

CORNER MONUMENT 1" Iron pipe with 4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 7-12-63

WITNESSES TO CORNER..... 5" S. Maple (1/4 S.) (N.B.T.) S. 12° E., 19 lks.



5" Y. Birch (1/4 S.) (N.B.T.) S. 81° W., 04 lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

The Corner was placed midway and one line bet. Sec. Cors.
Sg'd. Cedar stub found in near vicinity.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 1/7/64
REGISTERED LAND SURVEYOR