

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 46 N.R. 17W


Alger COUNTY

DESCRIPTION OF CORNER $\frac{1}{4}$ Cor. for Secs. 11 and 12.

CORNER MONUMENT 1" iron pipe with 4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 6-14-63

WITNESSES TO CORNER..... 10" Spruce ($\frac{1}{4}$ S.) (N.B.T.) S. 31° W., 47 Dks.



6" W. Pine ($\frac{1}{4}$ S. N.B.T.) N. 70° E., 43 $\frac{1}{2}$ Dks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line bet. Sec. Corners. No evidence of Original Cor.

SURVEYOR'S SEAL

SIGNED *Silly O. Buckler* DATE *4/2/64*
REGISTERED LAND SURVEYOR