## DEC 2 7 1999

AND C

Fo

## 70

Approve	ed by Alg	er Cou	nty
Land Sun	ev Remoi	numer	Hation
Peer Gro P.A. of 199	up Under	ACL	45 01 10 <i>66</i>
P.A. 01 199			1

ula	Que	orla	<u>v</u>
Ch	irmen		

SEULIUN	LAND CORNER RECORDATION CERTIFICA
	Filing Requirement of Act 74, Mich. P.A. 19
	SECTOR

05-184

Alger Located In: Corner Code # 46N R 17W 1. Public Land Survey T 41N R 1TW E13 \_ R R Property Controlling Т Τ\_ R in Section 3. Miscellaneous R Property in Section

DEC 1 5 1999 DONALD W. KINNUNEN

REGISTER OF DEEDS ALGER COUNTY MI Register of Deeds Stamp & File Number

TIME.

, Robert L. Jamros	, in a field survey on	April 16, 1999	. 19	

manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded

on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E1: PLS \* William A. Burt, DS, 1841. \* Set post corner of Sections 32 and 33 (T47N-R17W). \* Fir 12', N.23 E., 14 links. \* Sugar 6', N.47 W., 15 links. \* Sugar 18", S.70 W., 35 links. \* B.Ash 7", S.46 E., 19 links. \*\*\*\*\* George L. Depew, CS, 1915. \* Set iron corner from Government field notes. \* No references set. \* Recorded in the Minutes of County Surveys, Alger County Records. \*\*\*\*\* Michigan Department of Conservation, Forestry Division. \* Billy D. Buckler, RLS, 1957. \* Found 2" pipe with brass cap set by unknown. \* Re-witnessed section corner. \* 16" Y.Birch (S32 NBT), N.70 W., 47 links. \* 13" Elm (S5 NBT), S.07 W., 47 links. \* Liber 2, Page 203, Alger County Corner Records. \*\*\*\*\* Robert L. Jamros, RLS, 1988. \* Found 2° iron pipe with brass cap set by Alger County Surveyor, December 1915. \* Maple 4", N.66 W., 11.6 feet. \* Y.Birch 8", S.03 W., 13.9 feet. \* Spruce 12", N.46 E., 14.1 feet. \* Liber 3, Page 350, Alger County Corner Records. \* No other subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Located corner search area from previous survey work and standard field survey methods. Found 2' iron pipe with 3 1/4' brass cap correctly stamped, dated December 1915. \* Also found 3 reference trees from previous reports in good condition. \* Corner monument as found is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E1: Existing 2' iron pipe with 3 1/4' brass cap. \* Renewed existing reference trees with BT signs and paint. \* Established additional reference tree with BT signs, blazed, scribed and painted. \* Set PK nails with aluminum I.D. washers for measure in the following: Maple 5", S.37 E., 7.74 feet, "S4 BT". \* Existing - Y.Birch 10", S.01 W., 13.78 feet. \* Existing - Maple 5", N.61 W., 11.55 feet. \* Existing - Spruce 16', N.47 E., 13.96 feet. \* Survey marker sign on 6 foot steel post, S.62 W., 1.5 feet. \* All bearings are magnetic.

Signed by 25849 Surveyor's Michigan Lice#se No.

ROBERT L **JAMROS** PROFESSIONAL SHRVEYOR POFESSION!

OF MICH