

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 46 N.R. 17 W.


Alger COUNTY

DESCRIPTION OF CORNER 1/4 Corner for Sections 23 and 24.

CORNER MONUMENT 1" iron pipe with 4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 6/13/63

WITNESSES TO CORNER..... 9" Y. Birch (1/4 S.) (N.B.T.) S. 77° W. 27 Lks.



8" Y. Birch (1/4 S.) (N.B.T.) N. 12° E. 18 Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was placed Midway and on Line  
between Section Corners.

No evidence of Original Corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 7-29-63  
REGISTERED LAND SURVEYOR  
Billy D. Buckler