## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

		A	lger	COUNTY
		T 40	6 N	R 22 W
DESCRIPTION OF CORNER	$\frac{1}{2}$	6/15 1/22		
CORNER MONUMENT	15" O.D. iron pipe with 35" b	rass	cap dated	November 1915
DATE MONUMENT PLACED AND WITNESSED 10/19/69, F. J. Bray				
WITNESSES TO CORNER 12" Hemlock (S. 15) (NBT) N 59° E, 55½ links				
N 0 2' 2	8" Y. Birch (S. 16) (NBT) N	62° 1	W, 40 links	<u>;                                    </u>
	Iron Rail 5.0' high N	85°	E, Ol½ link	s
CIRCLE CORNER REGISTERED				<del></del>
DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.				

This corner was rewitnessed as set by County Surveyor in 1915.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED Tour Control REGISTERED LAND SURVEYOR

DATE 12/11/69

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing