## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

|  |   |            | Alger    |      | COUNTY        |
|--|---|------------|----------|------|---------------|
|  |   | τ          | 46 N     | _ ,  | R 22 W        |
| DESCRIPTION OF CORNER                                  | Section corner for sections                       | 17/<br>20/ |          |      |               |
| CORNER MONUMENT  | $1^{1_2^{11}}$ 0.D. iron pipe with $3^{1_2^{11}}$ | bra        | ss cap d | ated | November 1915 |
| DATE MONUMENT PLACED AND WITNESSED 8/18/69, F. J. Bray |   |            |          |      |               |
| WITNESSES TO CORNER                                    | Right bank of stream, west,                       | 51         | links    |      |               |
| No   | Right bank of stream, north,                      | , 80       | links    |      |               |
|  | No trees near.  AND                               |            |          |      |               |
| CIRCLE CORNER REGISTERE                                |   |            |          |      |               |

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was rewitnessed as set by County Surveyor in 1915, at that time one B.T. was found.

SURVEYOR'S SEAL

DISTRIBUTION:

REGISTERED LAND SURVEYOR Frank J. Bray

DATE 12/11/69

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing