SURVEY & REMONUMENTATION

Approved by Alger County Land Survey Floritonumentation Peer Group Under Act 345 of

JUL 3 0 1996

A. of 1990 On <u>5 /8</u> 19 <u>96</u>	
d print	
Merold W Carlon	
Chairman	•

COMMISSION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

4-385

For corners in		· · · · · · · · · · · · · · · · · · ·					
Alger (County)	Located In:	Corner Code #		FILED			
(000,47			TIMI	E_3:0	0p.m	<u></u>	
Public Land Survey	T <u>46N</u> R <u>18N</u> T <u>47</u> R T R	F-/3		JUN 27		- 1.	
Property Controlling in Section Miscellaneous	S T R S T R S T R		R	NALD W. H EGISTER OF ALGER COU	F DEEDS	EN	
Property in Section	ST R	.	Register of I	Deeds Stan	np & File	Numb	er
4. Lot No, F 5. Private Claims	Recorded Plat		A B	C D E	€ G H		K L
			3 4 7·	8	9 10	11-	12
do hereby certify that under rec in lines 1 and 2 above were in c manual of survey instructions Management or by a decree of	quirements of P.A. 74, Michigan P conformance with regulations and s of the United States Depart f a Court of Law and/or that the o	shruary 09, 1996 , 19 A. of 1970, the corner points ment rules therefore as required in the corner of the Interior, Bureau of corner points mentioned in lines 3, Board of Professional Surveyors or	ioned 6—18 urrent 7 Land 7 4 and 8—19	17	-1615	14-	13-
Decree of a Court of Law; esta as expressed below:	blished, re-established, monume	nted, re-monumented, recovered, t	found 10 30	29-	28 27	26-	25-
NOTE: Not more than 4 co on this certificate.	rners, all in the same town an	d range, may be recorded	11 12 — 31 13	32	33 34	35	36-
A. Description of original	monument and accessories	and/or subsequent restoration	,-				
F1: PLS-William A. Burt, [)S, 1841, Set qr. section pos	t - Sugar 12", N.11 E., 45 lin	ıks, Sugar 24°, N.	39 W., 9 li	nks . ****	k Walter	r ₩.

Gleason, Deputy CS, 1912, Iron corner set at the center of the straight line between section corners East and West. Lines run by Transit.***** Alger County Road Commission, George Depew, County Surveyor, 1915, Corner shown on road plans for the Grand Marais-Munising road as brass cap iron. No references given.**** Michigan State Highway Department, Project No. 02022, 1958, Highway plans for M-94, Corner position not shown on plans relative to centerline or survey centerline.***** Herbert L. Fluharty, RLS, 1977, Set 5/8° x 18° re-rod w/ RLS cap, equal distance and on line in centerline of blacktop road. Established the following references, P.Pole, S.65 E., 78.20 feet, P.Pole, N.33 E., 32.65 feet, Steel mail box post, S.28 W., 20.49 feet. Filing No. 89, Alger County Records.

B. Description of comer evidence found and/or method applied in restoring or reestablishing corner:

F1: Found 5/8" Rebar, cap missing, on centerline of existing asphalt road, County Hwy. H-58 East (old M-94). References of the 1977 report have been lost. Measurements to section corners East and West support the the method of reestablishment stated in the report of 1977. Old line fence bears North at East 1/16 corner position along this line. Monument position is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F1: Set Berntsen 3 1/4' aluminum cap, stamped to identify corner position, on existing 5/8' rebar and grouted in place with concrete. Established the following references. Steel fence post with 911 sign no. E10675, S.62 W., 69.65 feet.** P.Pole scribed BT at base, S.61 E., 76.66 feet.** Six foot steel fence post w/ survey marker sign, N.33 W., 60.03 feet.** Six foot steel fence post w/ survey marker sign, N.38 E., 53.82 feet. All bearings are magnetic.

Signed by Surveyor's Michigan License No.

No. 5849

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

RODERT L. JAMROS **PROFESSIONAL** SURVEYOR