SURVEY & REMONUMENTATION

Approved by Alger County Land Survey Remonumentation Peer Group Under Act 345 of

FEB 1 9 1998

A. 01 1930	Un 16-70 18-71
A.	1 - 1
77,22	ldulalson
	AND
17	kanwa n

SECTION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

05-71

For corners in		F.LED				
(County)	Located In:	Corner Code #	÷		0	
(5554)			TIME	8:30 F	H.M.	
	46 17 T <u>35</u> R 32	A3				
Public Land Survey	T R		DEC 17 1997			
	T 46NR 181					
	T R) W. KINNUM		
2. Property Controlling	T R ST R			TER OF DEED: R COUNTY, MI	-	
in Section	S T R		.32	n codivir. w		
3. Miscellaneous	S T R					
Property in Section	S T R		Register of Deeds Stamp & File Number			
. •		<u> </u>			, , , , , , , , , , , , , , , , , , , 	
4. Lot No, , f	Recorded Plat		А В	CDEFG	3 H E J	KIL
5. Private Claims	<u> </u>			Ĭ Ĭ Ī Ī		
			2 6—	5-4-4	_32_	
			*			
. Porant ! Timmon	No.	10 1007	4 7	8-1-9-		12-
do hereby certify that under re-	, in a field survey onR	venber 19, 1997 , 19 A. of 1970, the corner points menti	5			
		rules therefore as required in the cu		17 16	-1514 	13
•	•	nent of the Interior, Bureau of	1 1		111	
•		omer points mentioned in lines 3, a oard of Professional Surveyors or		20 21	-2223-	24-
	•	nted, re-monumented, recovered, f	· 91—1			
as expressed below:			10 30	29 - 28 -	-27-26-	25—
NOTE: Not more than 4 co	mers, all in the same town and	l range, may be recorded	11			\vdash
on this certificate.			12 31-	32 33	-3435-	36-
A Description of original	manument and accessories	and/or outposeurent vestaveticu	13			LL
L Description of original	monument and accessories a	and/or subsequent restoration	•			

43: PLS - William A. Burt, DS, 1841 * Set post corner of Sections 1 and 12 * Hemlock C4. 5.50 E., 38 links * White Pine 20, M.38 W., 31 links ***** William Ives, OS, 1850 * Hemlock 9, N.42 E., 18 links * Hemlock 8, S.42 E., 13 links ***** George E. Depew, County Euryeyor, 1915 ± Set standard iron corner from original field notes ***** J.R. Radcliffe, C.C.I. Co., Forestry Division, 1944 * Timber cruise sheet indicates brass cap and fences North and East ***** Frank J. Bray, RLS, Michigan Department of Conservation, 1965 * Found gaiv. From pipe w/3 inch brass cap * Corner was set by County Surveyor, dated 1915. Inacks with several stumps, badly rotten, which cossibly were original BT's * Set witness's - Hemlock 12, S.64 W., 16 links (dead-gown, 1997) * Hemlock 11, N.08 W., 32 links * Report .precorded ****

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

43: Found Alger County Standard Monument 4/3 inch brass cap, dated 1915, with 6 inch scribed, squared cedar post and 1 87 of the 1965 inrecorded report. Also found Hemlock 20, w/rusted yellow locator tag : Corner measures well between section corners North and South : Renewed exist. BY and established additional reference trees * Monumented corner position is accepted as a careful and faithful perpetuation of the corner position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

43: Exist. Alger County standard monument 4/3 inch brass cap, dated 1915 * Renewed exist. 37 4/87 signs and established additional reference trees w/BT signs, blazed and scribed * Set PK nails for measure w/Alum, I.C. wasners in the following - Exist. 3T, Hemlock 15, M.O4 W., 21.5 feet, dbl. blzd. * Hemlock 6, M.49 E., 19.8 feet, "BT" * Spruce 7, E.E. E., 14.2 feet, "BT" * Hemlock 6, S.62 W., 17.3 feet, "BT" * Exist. 6 inch scribed, squared cedar post, Southwest, 0.6 feet * Exist. Fellow, rusted locator tag on a Hemlock 23, 3.67 E., 28.5 feet * All bearings are magnetic.

25849 Surveyor's Michigan License No.

Date /Z

NIGAN STATE BOARD OF PROFES

JAMAGG PROFESCIO

> REVISED MAY 14, 1975 REVISED JAN. 1983