Approved by Albert County
Land Survey Finals, magazinion
Peer Group Under ADCE 5 of
P.A. of 1900 Cn 3-24 10.97

Marchal Carlos LAND CORNER RECORDATION CERTIFICATE

<-aa

Chairman	Filing Require	ment of Act 74, Mich. P.A	4. 1970
For corners in ALGER	Located In:	Corner Code #	
(County)			FILED
1. Public Land Survey	T 45N B 21W	01	TIME 2:00 fm
	T R	D 13	MAR 3 1 1997
2. Property Controlling in Section	S T R S T R		DONALD W. KINNUNEN REGISTER OF DEEDS
Miscellaneous Property in Section	S T R S T R		ALGER COUNTY, MI Register of Deeds Stamp & File Number
4. Lot No,	Recorded Plat		T.4GN. A.ZIW. DI3
5. Private Claims			2 6 5 4 3 2
Robert L. Jamros	, in a field survey onAuç	gust 30, 1996 . 19	4 7 8 9 10 11
to hereby certify that under n n lines 1 and 2 above were in manual of survey instructio Management or by a decree	equirements of P.A. 74, Michigan P.A. a conformance with regulations and ru- ons of the United States Department of a Court of Law and/or that the cor	of 1970, the comer points menti les therefore as required in the cu ant of the Interior, Bureau of the points mentioned in lines 3, 4	ioned 6 18 17 16 15 14 14 14 15 15 14 14 15 15 14 15 15 14 15 15 14 15 15 15 15 15 15 15 15 15 15 15 15 15
i above were in conformand Decree of a Court of Law; es is expressed below:	e with the rules of the Michigan Boatablished, re-established, monumente	ard of Professional Surveyors or ed, re-monumented, recovered, f	found 10 30 29 28 27 26 -
NOTE: Not more than 4 con this certificate.	corners, all in the same town and	range, may be recorded	11 32 33 34 34 35 35 31 31 31 31 31 31 31 31 31 31 31 31 31
-	al monument and accessories an		

L. Fluharty, RLS, 1975. * Found 3/4' Pipe at intersection of roads, Author unknown. P.P., N.45 E., 45.09 feet. * Stop sign base, N.2 W., 53.21 feet. * Stop sign base, S.17 E., 53.05 feet. * Recorded in L.1, P.76, Alger County Records. ***** Robert L. Jamros, RLS, 1990. * Alger County Road Commission Project for the rehabilitation of Tunteri Road from the Eben-Trenary Road East two miles to the intersection of State Highways M-94 and M-67. * Existing 3/4" Iron pipe monument at this corner position recovered during the centerline alignment and preliminary survey work for this project. Corner position documented on construction plans of Tunteri Road, Alger Count. * Not recorded.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D1: Established corner position by standard survey methods and references based on 1990 centerline alignment plans of the Tunteri Road Corner position lies 1.8 feet North of centerline of Tunteri Road and on centerline of gravel road North and South. Installed monumen at corner position and established references. Monumented corner position was established from the best available evidence and is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D1: Set 5/8" x 18" Rebar with a 3 1/4" Berntsen Aluminum cap no. RBD 5325, stamped to identify corner position. * Set PK nails with Aluminum I.D. washers for measure in the following reference objects. * Street sign 2 1/4° G.I.P., N.41 W., 47.19 feet. * Exist. BT, Power Pole, N.49 E., 44.94 feet to PK nail. * Power Pole, S.09 E., 134.95 feet to PK nail. * Cedar Post 4° no. 367, S.44 W., 44.64 fee to PK mail. * All bearings are magnetic.

Surveyor's Michigan License No.

1997

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983