

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T.47.. NR.17.W..

----- Alger ----- COUNTY

DESCRIPTION OF CORNER 1/4 Section Corner between Sections 8 and 17.

DESCRIPTION OF CORNER MONUMENT 2" gal. Iron Pipe with brass cap

WITNESSES TO CORNER 14" Cedar S 31° E 16 links

9" Cedar N 44° E 13 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

One Cedar B.T. in excellent condition.

Corner pipe set by unknown surveyor.

Corner found by Ken Killmar.

No new pipe set.

Corner placed and witnessed January 11, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 2/23/56
REGISTERED LAND SURVEYOR