

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 47. NR. 17 W.

Alger COUNTY

DESCRIPTION OF CORNER 1/4 Section Corner between Sections 5-8

DESCRIPTION OF CORNER MONUMENT 1" iron pipe with 4" brass cap

WITNESSES TO CORNER 16" Y. Birch S 21° E 28 links

12" Cedar N 87° W 29 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 Corner from one Cedar B.T. in poor condition; Notch and overgrowth remaining on stump.

Corner lies in Wet Swamp.

1/4 Corner found by Forestry Division Survey Crew while making a partial re-survey of this Township.

Corner placed and witnessed September 14, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 10/17/56  
REGISTERED LAND SURVEYOR