

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47. NR. 17 W.

Alger COUNTY

DESCRIPTION OF CORNER 1/4 Section Corner between Sections 8-9

DESCRIPTION OF CORNER MONUMENT 1" iron pipe with 4" brass cap

WITNESSES TO CORNER 15" Hard Maple S 54° E 30 links

7" Hard Maple S 1° W 17 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-established 1/4 Corner midway and on line between two Section Corners.

No evidence of original corner.

Location Poster placed on road.

Corner placed and witnessed September 14, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 10/17/56
REGISTERED LAND SURVEYOR