

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47. NR. 17. W.

A l g e r COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 4 and 5

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 6" Soft Maple (1/4" NBT) S 55° W 53 1/2 Links

7" Elm (1/4" NBT) S 60° E 22 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced from one possible B.T. (Hard Maple 16, west 23 links) which is hollow and interior decayed and decayed Birch stump in right direction, and distance checks well with proportionate distances N and S.

Corner was placed and witnessed August 15, 1960.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 9/15/60
REGISTERED LAND SURVEYOR
Billy D. Buckler