MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T_ 47 NR 17 T

			AlgerCOUNTY
DESCRIPTION	OF	CORNER	1/4 Corner between Sections 3 & 4
DESCRIPTION	OF	CORNER	MONUMENT_1"_Pipe_with_4" Brass_cap
WIT TNESSES	ТО	CORNER	12" Ceder - 8 47 E - 41 Links
			6* W. Birch - H 34 E - 15 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this Township. Two original B.T.'s still in place, in good condition.

Corner was placed and witnessed June 309 1954.

SURVEYORS SEAL

SIGNED LAND SURVEYOR DATE ____