MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T_47 NR_17.W ._

		Alger	COUNTY
DESCRIPTION	OF CORNER	1/4 Corner between Sections 9, 10	
DESCRIPTION	OF CORNER	MONUMENT_1" iron pipe with 4" brass cap	
WITNESSES .	O CORNER	10" Hard Maple S 8° E 55 link	S
		6" Hard Maple N 26° E U link	S

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-established 1/4 Midway and on line between two Section Corners.

No evidence of original Corner.

Corner placed and witnessed December 18, 1956.

SURVEYORS SEAL

SIGNED Billy D'Buckles DATE 1/7/57 __