

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47. NR. 17 N.

Alger COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Section 9, 16

DESCRIPTION OF CORNER MONUMENT No new pipe set.

WITNESSES TO CORNER 10" Hard Maple S 68° E 18 links
Marked "1/4 S NBT"
12" Hard Maple N 20° W 50 1/2 links
Marked "1/4 S NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

2" pipe with brass cap set by unknown Surveyor.

One Hard Maple tree in proper position. "Probable B.T."

Position checks for distance E - W.

Corner re-witnessed December 18, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 1/7/57
REGISTERED LAND SURVEYOR