

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47-48NR 17 W

Alger

COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 31, 6

DESCRIPTION OF CORNER MONUMENT 1" iron pipe with 4" brass cap

WITNESSES TO CORNER 10" Hard Maple N 34° E 32 links

14" Hard Maple N 70° W 14 1/2 links

Distance measured from Brass Cap to Notch.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 Corner from two Y. Birch B.T.s; down, poor condition.

Old stake in place.

1/4 Corner found by Forestry Division Survey Crew while making re-survey of this Township.

Corner placed and witnessed October 25, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 11/8/56
REGISTERED LAND SURVEYOR