

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47. NR. 17. W.

Alger

COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 6, 7

DESCRIPTION OF CORNER MONUMENT 1" iron pipe with 4" brass cap

WITNESSES TO CORNER 14" Cedar N 6° W 31 links
Marked 1/4 S NBT

14" Cedar N 73° W 20 links
Marked 1/4 S NBT

Distance measured from Brass Cap to Notch

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 Corner from one Cedar B.T. (down).

Cedar marked for Corner in place.

1/4 Corner lies on south bank of small stream.

Corner found by Forestry Division Survey Crew while making a re-survey of this Township.

Corner placed and witnessed October 25, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 11/8/56
REGISTERED LAND SURVEYOR