

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47. NR. 17 W.

Alger COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 2-11

DESCRIPTION OF CORNER MONUMENT 1" iron pipe with 4" brass cap

WITNESSES TO CORNER 14" Hard Maple N 27° W 58 links

9" Soft Maple N 73° E 12 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-established 1/4 Corner midway and on line between two section corners.

No evidence of original corner.

Corner placed and witnessed September 13, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buchler DATE 10/16/56
REGISTERED LAND SURVEYOR