

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47. NR. 17. W.

Alger COUNTY

DESCRIPTION OF CORNER 1/4 Section Corner between Sections 10-11

DESCRIPTION OF CORNER MONUMENT 1" iron pipe with 4" brass cap

WITNESSES TO CORNER 12" Hard Maple S 41° W 38 links

12" Hard Maple N 56° W 26 links

10" Hard Maple N 68° E 23 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-established 1/4 Corner midway and on line between two Section Corners

No evidence of original corner.

Corner placed and witnessed Sept. 17, 1956.

SURVEYORS SEAL

SIGNED

Billy D. Buckles
REGISTERED LAND SURVEYOR

DATE 10/17/56-