

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 47. NR. 17. W. . .

----- Alger ----- COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 2-3 -----

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap -----

WITNESSES TO CORNER 10" Hard Maple N 87° W 32 links -----

8" Soft Maple N 40° E 19 links -----

-----

-----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 Corner from one Hemlock B.T. in poor condition. Stump rotted badly.

1/4 Corner found by Forestry Division Survey Crew while making a re-survey of this Township.

Corner placed and witnessed September 13, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 10/15/56  
REGISTERED LAND SURVEYOR