## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T.47. NR. 17. W.

|             |    |        | MerCOUNTY                           |
|-------------|----|--------|-------------------------------------|
| DESCRIPTION | OF | CORNER | 1/4 Corner between Sections 26 & 35 |
| DESCRIPTION | OF | CORNER | MONUMENT 1" Pipe with 4" Bress cap  |
| WIT TNESSES | то | CORNER | 12" Cedar - S 27 E - 28 Links       |
|             |    |        | 12" Ceder - R 34 E - 25 Utn's       |
|             |    |        |                                     |
|             |    |        |                                     |

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this Township. Corner had been previously located by unknown. Two original B.T.'s still in place, down, one in good condition, one poor.

Corner was placed and witnessed June 22, 1954.

SURVEYORS SEAL

SIGNED LAM C. DATE 2/25/55 PAGESTERED LAND SURVEYOR