MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_47 NR_17 W __

			Alger	COUNT
DESCRIPTION	OF	CORNER	1/4 Section Corner between Sections 17 and	20
DESCRIPTION	OF	CORNER	MONUMENT 1" pipe with 4" brass cap	
WIT TNESSES	то	CORNER	12" Hemlock N 40 N _ 54 links	
			6" Cedar N 75° E23 links	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replace 1/4 Corner from one W. Pine B.T. (good condition).

Corner found by Ken Killmar.

Corner placed and witnessed January 11, 1956.

SURVEYORS SEAL

SIGNED SILLY SURVEYOR DATE _ 2/14/56