MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_47 NR_17_W __

					- -	Alger			_ COUNT	Y
DESCRIPTION	OF	CORNER	Secti	ou Corne	c comm	on to Sec	tions	16, 17, 2	20 , 21	
DESCRIPTION	OF	CORNER	MONU	MENT	Su gal	. Iron pi	pe_wit	h brass_c	cap	
WIT TNESSES	то	CORNER	1	4" White	Pine_	_N_51°.	W41	à linke _	. -	-
				9" Cedar	· - ,	_ § 24°	W _ 22	_links_		
						- -				
						. .				
						. <u>-</u>				
DESCRIPTION IN	ı De	TALL AS	TO HOW	CORNER	WAG	LOCATED	AND	DENTIFIED	. 08	
RESTORED.		INIL AS	io now	CORNER	MUS	COUNTED	NAU	DEN HITTED	- OR	

One Cedar B.T. in excellent condition.

Corner set by unknown surveyor.

Corner found by Ken Killmar.

Corner placed and witnessed January 11, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE _2/23/56