

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47 ... NR. 17W ...

Alger COUNTY

DESCRIPTION OF CORNER ... 1/4 Cor. between Secs: 11-14 ...

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap ...

WITNESSES TO CORNER ... 8" S. Maple (1/4s NBT) South 2 Lks. ...

13" H. Maple (1/4s NBT) N69°W 32 Lks. ...

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 Cor. from one Y. Birch B.T. bearing north 4 Lks. B.T. in poor condition. Found by Forestry Division Survey Crew. Placed and wit. 9/10/58 with Bill Wallace, Ass't D.F.

SURVEYORS SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 7/28/59
REGISTERED LAND SURVEYOR