

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T47-48 NR 16-17W

Alger

COUNTY

DESCRIPTION OF CORNER Sec. Cor. 1-36-31-6 also Twp. Cor.

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 4" H. Maple (S31 NBT) N5°E 23 Lks.

8" S. Maple (S1 NBT) S50°W 13 Lks.

8" S. Maple (S1 NBT) S6°W 30 Lks.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-witnessed Cor. as set by unknown surveyor. Found 3/4" Iron Pipe in place. Also found site of two probable B.Ts. Beech N25°E 41 Lks. tree down, rotted badly. Sugar S29°W 42 Lks. stump bottom, badly rotted.

SURVEYORS SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 7/28/59
REGISTERED LAND SURVEYOR