

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47 .. NR. 17W ..

----- Alger ----- COUNTY

DESCRIPTION OF CORNER ... 1/4 Cor. between Secs: 11-12

DESCRIPTION OF CORNER MONUMENT ... 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER ... 9" H. Maple (1/4s NBT) N64⁰W 16 1/2 Lks.

... 8" H. Maple (1/4s NBT) N85⁰E 22 Lks.

... 9" H. Maple (1/4s NBT) S4⁰W 50 Lks.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 cor. from two H. Maple B.Ts. bearing S32⁰W 11 Lks.;
tree down in poor condition. Found several scribe marks on
overgrowth. Found remains of H. Maple down and rotted N63⁰E
12 Lks. Cor. lies on slope facing north. Cor. placed and wit.
9/16/58 with Bill Wallace, Ass't D.F.

SURVEYORS SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 7/29/59
REGISTERED LAND SURVEYOR