

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47 NR 17-18 W

Alger

COUNTY

DESCRIPTION OF CORNER Section corner common to Sec.'s 6-7-1-12

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 14" Hard Maple S 22° E 46 links

"S 7 NBT"

18" Hard Maple N 7° W 29 links

"S 1 NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced section corner from two yellow birch B.T.s. Both trees in good condition bearing S 18° E 36 links and N 63° W 30 links.

Corner found by Forestry Division Survey Crew.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 11/4/57
REGISTERED LAND SURVEYOR