

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47 .. NR 17 W. . . .

Alger

..... COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 15, 16, 21, 22 .

DESCRIPTION OF CORNER MONUMENT No new pipe set.

WITNESSES TO CORNER 9" Hard Maple N 60° W 22 links
Marked "S 16 NBT"

12" Hard Maple N 15° E 30 links
Marked "S 15 NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-witnessed Section Corner

2" Pipe with Brass cap set by unknown Surveyor.

Hard Maple Stub., Broken off, in proper position. B.T.

No new pipe set.

Re-witnessed December 12/18/50.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 1/7/57
REGISTERED LAND SURVEYOR