Cons. 4047 4/55

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T-46-47 NR \_ 17 \_ W

				Ale	L <b>r</b>		COUNTY
DESCRIPTION	OF	CORNER	1/4 corner	between Sec	rtions 33	and 4	
DESCRIPTION	OF	CORNER	MONUMENT	1º Pipe	yith in	Brass_Cap	
WITNESSES	то	CORNER .	7" Soft M	ple (1/4e H	BT)	1 65° W	22_Links
			10°_89C 14	ple (1/60 )	<b>BT)</b> {	£ 04° <b>E</b> _	26 Idnks
					<b></b>		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was placed midway and on line between section corners. No evidence of original corner.

Corner was placed and witnessed August 15, 1960.

SURVEYORS SEAL

SIGNED Silly D. Buckler DATE 9/15/60\_
REGISTERED LAND SURVEYOR

RILLY D. Buckler